



Three-view drawing illustrates configuration and gives key dimensions of Lockheed's L-1011 three-turboprop transport design.

diamond grinding mills and saw blades. Even so, the boron and glass filaments are abrasive and tend to wear out cut-

In the area of conventional machine tools, the Air Force Manufacturing Technology Div. has several contracts

them, all silicones, produced condensable deposits of methyl silicone compounds that had the same basic structure